



Informe Provisional

# Informe Provisional

## Datos del Suceso

<b>File number</b>	44076210/21	
<b>Occurrence class</b>	<b>Accident</b>	
<b>Occurrence category</b>	ADRM: Aerodrome GCOL: Ground Collision	
<b>Occurrence status</b>	Factual	
<b>UTC date/time</b>	17/5/2021	20:10
<b>State/area of occ</b>	South America Argentina	
<b>Location name</b>	Ad. Mercedes - Pcia de Buenos Aires	
<b>Latitude of occ</b>	34:38:22 South	
<b>Longitude of occ</b>	59:24:20 West	

## Reseña del Vuelo

El 17 de mayo de 2021 la aeronave matrícula LV-ATE, un Cessna A152, despegó del aeródromo de Morón (Buenos Aires) con destino el aeródromo de Mercedes (Buenos Aires) en un vuelo de aviación general de entrenamiento.

Luego de un vuelo sin inconvenientes, la aeronave aterrizó en Mercedes. Posteriormente, iniciando el vuelo de retorno a Morón, durante el rodaje hacia la pista 01, la aeronave impactó contra una zanja.

El accidente ocurrió de día y en condiciones de buena visibilidad.

## Información del Vuelo

<b>Last departure point</b>	Argentina Other (MRD - Ad Mercedes. Pcia de Buenos Aires)
<b>Planned destination</b>	Argentina SADM : Moron, Ba
<b>Duration of flight</b>	0,1 Hour(s)
<b>Call sign</b>	LV-ATE



Flight phase	Taxi
--------------	------

### Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft				1		1
Grand total				1		1

### Información de la Aeronave

Aircraft registration	LV-ATE
State of registry	Argentina
Aircraft damage	Substantial
Manufacturer/model	CESSNA A152
Aircraft category	Fixed Wing Aeroplane Small Aeroplane Small Aeroplane
Year built	1981
Serial number	0998
Maximum t/o mass	757 kg
Mass group	0-2 250 kg
Total cycles a/c	
Aircraft total time	28409,8 Hour(s)
Maintenance docs	Current
Airworthiness cert.	Valid

### Información del Motor

Engine position	1
Manufacturer/model	LYCOMING 235 FAMILY
Engine serial number	L-22892-15
Time since new	22441,2 Hour(s)
Engine cycles	



<b>Time since overhaul</b>	<i>1235,1 Hour(s)</i>
<b>Cycles since overhaul</b>	
<b>Time since inspection</b>	<i>52,5 Hour(s)</i>

#### Información de la Hélice

<b>Prop position</b>	<i>1</i>
<b>Make of propeller</b>	<i>SENSENICH</i>
<b>Propeller model</b>	
<b>Prop serial</b>	<i>K11336</i>
<b>Time since new</b>	
<b>Time since overhaul</b>	<i>1528,4 Hour(s)</i>
<b>Time since inspection</b>	

#### Información sobre el Personal

<b>Age</b>	<i>29 Year(s)</i>	<b>Gender</b>	<i>Male</i>
<b>Category</b>	<i>Pilot-in-command</i>		
<b>License type</b>	<i>Aeroplane pilot Private pilot</i>		
<b>License issued by</b>	<i>State of Registry</i>		
<b>Ratings</b>	<i>Rating not required</i>		
<b>Experience all a/c</b>	<i>35,8 Hour(s)</i>	<b>Experience this a/c</b>	<i>35,8 Hour(s)</i>
<b>Experience all-90 days</b>	<i>35,8 Hour(s)</i>	<b>Experience on a/c-90 d</b>	<i>35,8 Hour(s)</i>
<b>Experience all-24 hours</b>	<i>0,9 Hour(s)</i>	<b>Experience on a/c-24 h</b>	<i>0,9 Hour(s)</i>

#### Información Meteorológica

<b>Weather relevant</b>	<i>No</i>
<b>Weather conditions</b>	<i>VMC</i>
<b>Visibility</b>	
<b>Light conditions</b>	<i>Daylight</i>
<b>Wind description</b>	
<b>Wind direction</b>	



**Wind speed**

Speed measured at

Wind gusts

**Información sobre el Lugar del Suceso**

**Wreckage location** *On aerodrome/airstrip*

**Terrain type** *Level/flat*

**Elevation terrain** *111 ft*

**Surface type** *Other*

**Length wreckage trail**

**Rwy exit at**

**Dist to exit**

**Información sobre el Operador**

**Operation type** *Non-Commercial Operations  
Flight Training/Instructional  
Solo*

**Schedule type** *Non-scheduled*

**Operator** *Argentina  
Private Operator*

**Operator type** *Flying club/school*

**Estado de la Investigación**

**Investigation Progress** *La investigación se encuentra en la fase de redacción del Proyecto de Informe de Seguridad Operacional (PISO).*



Ministerio de Transporte  
**Argentina**

**JST** | SEGURIDAD EN  
EL TRANSPORTE

**Corrective Actions /  
Safety  
Recommendations**