



Informe Preliminar

Informe Preliminar

Datos del Suceso

File number	112293404/21	
Occurrence class	Accident	
Occurrence category	GCOL: Ground Collision	
Occurrence status	Initial notification	
UTC date/time	18/11/2021	12:30
State/area of occ	South America Argentina	
Location name	Aeródromo de Morón	
Latitude of occ	34:40:45 South	
Longitude of occ	58:38:34 West	

Reseña del Vuelo

En un vuelo de aviación general, la aeronave ingresa por rodaje "Echo" en dirección a la plataforma norte. Durante el ingreso a esta plataforma se produce la colisión de la aeronave con un camión abastecedor de combustible.

Información del Vuelo

Last departure point	Argentina SADM : Moron, Ba
Planned destination	Argentina SADM : Moron, Ba
Duration of flight	0,5 Hour(s)
Call sign	LV-CDW



Flight phase	<i>Taxi</i>
--------------	-------------

Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground				1		1
Total on aircraft				1		1
Grand total				2		2

Información de la Aeronave

Aircraft registration	<i>LV-CDW</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Substantial</i>
Manufacturer/model	<i>CESSNA 150 M</i>
Aircraft category	<i>Fixed Wing Aeroplane Small Aeroplane Small Aeroplane</i>
Year built	<i>1977</i>
Serial number	<i>15079201</i>
Maximum t/o mass	<i>725 kg</i>
Mass group	<i>0-2 250 kg</i>
Total cycles a/c	
Aircraft total time	<i>10589,3 Hour(s)</i>
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>



Información del Motor

Engine position	1
Manufacturer/model	CONTINENTAL (TELEDYNE) USA 200 FAMILY (O-200-A)
Engine serial number	254248
Time since new	7641 Hour(s)
Engine cycles	
Time since overhaul	1740 Hour(s)
Cycles since overhaul	
Time since inspection	

Información de la Hélice

Prop position	1
Make of propeller	MCCAULEY PROPELLER SYSTEMS
Propeller model	1A101/HCM6950
Prop serial	G11396
Time since new	
Time since overhaul	
Time since inspection	

Información sobre el Personal

Age	29 Year(s)	Gender	Female
Category	Pilot-in-command		
License type	Aeroplane pilot Private pilot		
License issued by	State of Registry		
Ratings	Held required rating		



Experience all a/c	<i>186,6 Hour(s)</i>	Experience this a/c
Experience all-90 days		Experience on a/c-90 da
Experience all-24 hours		Experience on a/c-24 ho

Información Meteorológica

Weather relevant	<i>No</i>
Weather conditions	<i>VMC</i>
Visibility	
Light conditions	<i>Daylight</i>
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Información sobre el Lugar del Suceso

Wreckage location	<i>On aerodrome/airstrip</i>
Terrain type	<i>Level/flat</i>
Elevation terrain	
Surface type	<i>Pavement</i>
Length wreckage trail	
Rwy exit at	
Dist to exit	

Información sobre el Operador

Operation type	<i>Non-Commercial Operations Flight Training/Instructional Solo</i>
Schedule type	<i>Non-scheduled</i>
Operator	<i>Argentina</i>



	<i>Private Operator</i>
Operator type	<i>Flying club/school</i>

Líneas de Investigación

Descr factor subject	<i>Aerodrome generally Aerodrome operations Vehicle/equipment operations</i>
Factors justification	<i>Procedimientos de movimiento de vehículos dentro de las áreas de maniobras.</i>