



Informe Provisional

Informe Provisional

Datos del Suceso

File number	13475674/20	
Occurrence class	Serious incident	
Occurrence category	SCF-NP: System/component failure or malfunction [non-powerplant]	
Occurrence status	Factual	
UTC date/time	1/3/2020	17:35
State/area of occ	South America Argentina	
Location name	Aeropuerto Internacional de Neuquén	
Latitude of occ	38:56:56 South	
Longitude of occ	68:09:21 West	

Reseña del Vuelo

Durante un vuelo regular (AU2667) desde Bariloche al Aeroparque Jorge Newbery, se produjo una falla en el sistema de presurización y posterior aterrizaje de emergencia en Neuquén. Se accionó sistema de mascarar.

Información del Vuelo

Last departure point	Argentina SAZS (BRC) : San Carlos De Bariloche, Rn
Planned destination	Argentina SABE (AEP) : Buenos Aires/Aeroparque, Jorge Newbery, Cf
Duration of flight	1,4 Hour(s)
Call sign	AU2667
Flight phase	En route



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft				93		93
Grand total				93		93

Información de la Aeronave

Aircraft registration	<i>LV-CIF</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>None</i>
Manufacturer/model	<i>EMBRAER ERJ190</i>
Aircraft category	<i>Fixed Wing Aeroplane Large Aeroplane Large Aeroplane</i>
Year built	<i>2011</i>
Serial number	<i>19000421</i>
Maximum t/o mass	<i>51800 kg</i>
Mass group	<i>27 001 to 272 000 kg</i>
Total cycles a/c	<i>16819</i>
Aircraft total time	<i>23269 Hour(s)</i>
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>

Información del Motor

Engine position	<i>1</i>
Manufacturer/model	<i>GENERAL ELECTRIC USA CF34-10 Series (CF34-10E5A1)</i>
Engine serial number	<i>994700</i>
Time since new	<i>21897 Hour(s)</i>
Engine cycles	<i>14832</i>
Time since overhaul	



Cycles since overhaul
Time since inspection

Información del Motor

Engine position	2
Manufacturer/model	GENERAL ELECTRIC USA CF34-10 Series (CF34-10E5A1)
Engine serial number	994992
Time since new	20609 Hour(s)
Engine cycles	14959
Time since overhaul	
Cycles since overhaul	
Time since inspection	

Información sobre el Personal

Age	51 Year(s)	Gender	Male
Category	Pilot-in-command		
License type	Aeroplane pilot Airline transport pilot		
License issued by	State of Registry		
Ratings	Held required rating		
Experience all a/c	16500 Hour(s)	Experience this a/c	3500 Hour(s)
Experience all-90 days	140 Hour(s)	Experience on a/c-90 d	140 Hour(s)
Experience all-24 hours	6 Hour(s)	Experience on a/c-24 h	6 Hour(s)

Información sobre el Personal

Age	37 Year(s)	Gender	Male
Category	Co-pilot		
License type	Aeroplane pilot Airline transport pilot		
License issued by	State of Registry		



Ratings	<i>Held required rating</i>		
Experience all a/c	<i>6500 Hour(s)</i>	Experience this a/c	<i>3500 Hour(s)</i>
Experience all-90 days	<i>130 Hour(s)</i>	Experience on a/c-90 d	<i>130 Hour(s)</i>
Experience all-24 hours	<i>3,5 Hour(s)</i>	Experience on a/c-24 h	<i>3,5 Hour(s)</i>

Información Meteorológica

Weather relevant	<i>No</i>
Weather conditions	<i>Unknown</i>
Visibility	
Light conditions	<i>Daylight</i>
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Información sobre el Operador

Operation type	<i>Commercial Air Transport Passenger Airline</i>
Schedule type	<i>Scheduled</i>
Operator	<i>Argentina Austral Lineas Aereas</i>
Operator type	<i>Private owner</i>

Estado de la Investigación

Investigation Progress	<i>A la espera de información correspondiente al entrenamiento de la tripulación.</i>
-------------------------------	---



Ministerio de Transporte
Argentina

JST | SEGURIDAD EN
EL TRANSPORTE

**Corrective Actions /
Safety
Recommendations**