



Informe Preliminar

Informe Preliminar

Datos del Suceso

File number	3501911/23	
Occurrence class	Incident	
Occurrence category	RAMP: Ground Handling	
Occurrence status	Initial notification	
UTC date/time	10/1/2023	01:20
State/area of occ	South America Argentina	
Location name	Ap. Int. Taravella (SACO)	
Latitude of occ	31:18:36 South	
Longitude of occ	64:12:30 West	

Reseña del Vuelo

Durante un vuelo de aviación comercial regular, al momento de retirar la escalera móvil de la puerta trasera de la aeronave, se produjo un impacto sobre la superficie del fuselaje que provocó daños al mismo.

Información del Vuelo

Last departure point	Argentina SACO (COR) : Cordoba, Cba
Planned destination	Argentina SABE (AEP) : Buenos Aires/Aeroparque, Jorge Newbery, Cf
Duration of flight	0 Hour(s)
Call sign	JES3268
Flight phase	Standing



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground	0	0	0	0	0	0
Total on aircraft	0	0	0	155	0	155
Grand total	0	0	0	155	0	155

Información de la Aeronave

Aircraft registration	<i>LV-IVN</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Minor</i>
Manufacturer/model	<i>AIRBUS A320 200 232</i>
Aircraft category	
Year built	
Serial number	<i>8730</i>
Maximum t/o mass	
Mass group	<i>27 001 to 272 000 kg</i>
Total cycles a/c	
Aircraft total time	
Maintenance docs	
Airworthiness cert.	

Información sobre el Personal

Age	<i>40 Year(s)</i>	Gender	<i>Male</i>
Category	<i>Pilot-in-command</i>		
License type	<i>Aeroplane pilot Airline transport pilot</i>		
License issued by	<i>State of Registry</i>		
Ratings	<i>Held required rating</i>		
Experience all a/c		Experience this a/c	



Experience all-90 days	Experience on a/c-90 d
Experience all-24 hours	Experience on a/c-24 h

Información sobre el Personal

Age	26 Year(s)	Gender	Male
Category	Co-pilot		
License type	Aeroplane pilot Airline transport pilot		
License issued by	State of Registry		
Ratings	Held required rating		
Experience all a/c		Experience this a/c	
Experience all-90 days		Experience on a/c-90 d	
Experience all-24 hours		Experience on a/c-24 h	

Información Meteorológica

Weather relevant	
Weather conditions	VMC
Visibility	
Light conditions	Night/dark
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Supervivencia

Survivability	Yes
Locating method	
ELB-A, ELT status	
Pilot restraint system	
Co-pilot restraint system	
Escape time	



Información sobre el Operador

Operation type *Commercial Air Transport*
Passenger
Airline

Schedule type *Scheduled*

Operator *Argentina*
Private Operator

Operator type *Private owner*

Líneas de Investigación

Descr factor subject *Aerodrome generally*
Aerodrome equipment/facilities
Ramp service equipment and vehicles
Ramp service vehicle
Passenger steps/stairs vehicle

Factors justification